

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 25, 30, 31 and 36, Township 3 North, Ranges 5 & 6 West, W.M., Tillamook and Washington Counties, Oregon.

ORIGINAL

Stake, now missing, from which a:

- 2 1/2" Cedar bears N30E 35 lks; now missing.
- 4 1/2" Fir bears S45E 12 lks; now 46" stump, scribe marks S31 exposed.
- 2 1/2" Cedar bears S22°15'W 23 lks; now 28" down stub.
- 1 1/2" Cedar bears N83°15'W 35 lks; now 17" tree S83W, exposed scribe mark T, rest of face burnt out.

RESTORED CORNER AND REWITNESSED CORNER POINT

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R6W R5W S25 S30 S36 S31 1952 2311," 2 1/2' in ground, from which a:

- 4" Fir bears S24°30'W 37.9'; scribed S36 BT.
- 16" Fir bears N33E 38.5'; scribed T3N R5W S30 BT RE 2311.
- 7" Fir bears N60W 25.6'; scribed T3N R6W S25 BT.
- 7" Fir bears S70E 34.2'; scribed T3N R5W S31 BT.


Found a 2" iron pipe bears S50W 0.9'.

Placed an Oregon State Board of Forestry metal location poster on 4" Fir and marked it: Sec 25 T3N R6W Sec Cor 3.2 Ft. S82E.

Dated November 24, 1952.

This corner was restored by Don D. Davis,  
Don D. Davis Assistant Forest Engineer

under my direction.



Present and witnessed by R. A. Young, Compassman.

Present and witnessed by G. M. Schwalen, Chairman.