

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 7 and 8,
Township 2 North, Range 7 West, W.M., Tillamook County,
Oregon.

ORIGINAL

Stone 18" x 13" x 10", $\frac{1}{4}$ on West face, 12" in ground
(in place), from which a:

- 40" Hemlock bears S40 $\frac{1}{2}$ W 14 lks.;
now 42" stub 6 ft. high, burned out face.
- 40" Fir bears S79E 17 lks.;
now 42" partly uprooted stub 10 ft.
high, no face visible.

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze
cap marked "OREGON STATE BOARD OF FORESTRY
 $\frac{1}{4}$ S7 S8 1953 2311," 30 inches in ground, on
South side original stone, in mound of rock,
and from which a:

- 48" Fir stub 18 ft. high bears N19W 36.2 ft.;
scribed $\frac{1}{4}$ S7 BT RE 2311.
- 38" Fir snag bears S21E 25.1 ft.;
scribed $\frac{1}{4}$ S8 BT.

Oregon State Board of Forestry metal location poster
on 38" Fir snag BT.
Crown-Zellerbach poster on 48" Fir stub BT.
Also State poster on 4" x 4" x 48" white Cedar
post 2 ft. North of pipe.
Crown-Zellerbach tag on North edge road
620 ft. North of corner.

Dated November 12, 1953.

Restored by Richard Morris, under
my direction. Richard Morris, Compassman



Present and witnessed by Carl Vold

Robert Schumacher