

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 10, 11, 14 and 15,
T. 3 N., R. 6W., W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 36" Cedar bears N57 $\frac{1}{2}$ °E 4 lks.; now 30" by 7 ft. high stub, original axe marks remaining.
- 10" Hemlock bears S78 $\frac{1}{2}$ °E 27 lks.; now 10" by 2 ft. stub.
- 12" Hemlock bears S49 $\frac{1}{2}$ °W 14 lks.; roots remaining in place.
- 20" Cedar bears N66°W 25 $\frac{1}{2}$ lks.; now 23" stump scribes BT remaining.

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R6W S10 S11 S14 S15 1955 RE 2311," 32 inches in ground, and from which a:

- 6" Fir bears N78°E 34.4 ft.; scribed T3N R6W S11 BT.
- 12" Fir bears S66°E 3.5 ft.; scribed T3N R6W S14 BT RE 2311.
- 11" Fir bears S70°W 19.1 ft.; scribed T3N R6W S15 BT.
- 10" Fir bears N64°W 23.5 ft.; scribed T3N R6W S10 BT.

Set 4" x 4" x 72" white painted Cedar post 2 ft. NW of pipe.

Oregon State Board of Forestry metal location poster on 12" Fir BT.

Also poster on 6" Fir on N edge old cat road 100.0 ft. N of corner.

Dated November 17, 1955.

Restored by Richard A. Morris under my direction.
Richard A. Morris, Transitman



Present and witnessed by Robert Sturm
Lloyd Geraths
Forrest Logan