

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 4, 5, 8 and 9,
T. 3N., R. 6W., W.M., Tillamook County, Oregon.

ORIGINAL

Post, now only rotted point in place from which a:

- 30" Fir bears N42°E 35½ lks.; 30" stump, scribe N visible, rest unexposed.
- 40" Fir bears S31°E 24 lks.; 38" stump, scribes 3N R6W S9 visible, rest unexposed.
- 30" Fir bears S65½°W 5 lks.; 31" stump, scribes 6W S8 visible, rest unexposed.
- 20" Fir bears N28°10'W 72 lks.; 29" stump remaining lower face unexposed.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R6W S4 S5 S8 S9 1955 RE 2311," 33 inches in ground, in mound of stone, and from which a:

- 12" Hemlock bears S50°W 48.8 ft.; scribed T3N R6W S8 BT RE 2311.
- 11" Hemlock bears S56°E 79.7 ft.; scribed T3N R6W S9 BT.
- 14" Hemlock bears N54°W 43.0 ft.; scribed T3N R6W S5 BT.

Set 4" x 4" x 72" white painted cedar post 1 ft. NE of pipe. Oregon State Board of Forestry metal location poster on 14" Hemlock BT.

Also poster on 4" x 4" x 72" white painted Cedar post on N edge road 128.0 ft. South.

Also old poster on 8" Hemlock on S edge road approx. 4 chs. N.

Dated November 16, 1955.

Restored by Richard A. Morris under my direction.
Richard A. Morris



Present and witnessed by Forrest Logan
Lloyd Geraths
Robert Sturm