

395

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 12 and 13,
T2N, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

Stone 15"x9"x5" (missing) from which a:

34" Hemlock bears S20°W 12 lks.; now 33" snag, portion of
scribe visible on burnt face.

7" Hemlock bears N33°E 31 lks.; now just roots remaining
in place.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap
marked "OREGON STATE BOARD OF FORESTRY ¼ S12 S13 1957
RS 401," 33 inches in ground, in mound of stone,
and from which a:

38" Fir stump bears N2°W 75.4 ft.; scribed ¼ S12 BT.

43" Fir stump bears S67°W 5.6 ft.; scribed ¼ S13 BTRS 401.

Oregon State Board of Forestry metal location poster on
43" Fir stump BT.

Set 4"x4"x60" white painted Cedar post 1.5' NE.

Dated August 1, 1957.

Restored by



Richard A. Morris

MAY 10, 1957

Richard A. Morris

401

Present and witnessed by Robert Sturm
Harold Russell