

CHAINS

Rewitnessing of Sec Cor 27, 28, 33, & 34, T 1 S, R 10 W, W.M.

Found a 3/4 " galvanized iron pipe 1 foot out of the ground and marked by a 3 foot yellow iron stake. Found old BT, 60" Spruce with a Yellow Tag bearing S 47 1/2 W 28.4 feet. with original scribe marks still visable. Other evidence of the corner was found as follows:

- N 71 E 7.3 feet there bears a 10" rotted stub uproot.
- S 42 E 20.5 feet there bears an 8" stub and log with a 39" rotted face but no scribing visable.
- N 32 1/2 W 31.0 feet there bears a large rotten stump.

All of this evidence corresponds with the description of BT's as given in the original notes. The corner was then rewitnessed as follows: Var. 21 1/2 E.

- Hemlock 11" bearing N 51 E 16.6 feet marked "BT S 27 # 376"
 - Hemlock 18" bearing N 19 1/4 W 35.2 feet marked "BT S 28 #376"
 - Hemlock 28" bearing S 64 1/2 E 28.0 feet marked "BT S 34 #376"
- This tree also bears the cruiser marks "A. ~~AK~~"

March 16, 1960
 In the presence of:
 Roswell K. Miller
 Donald McFarland

Charles G. Collard
 Charles G. Collard
 Registered Land Surveyor
 Oregon # 376