

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

One quarter corner common to Sections 17 and 20, T2S,
R8W, W.M., Tillamook County, Oregon.

ORIGINAL

Post, missing, from which a:

- 12" Hem. bears N47W 61 lks.; now badly burnt stump, back cast of upper face with scribe S remaining, scribe T on lower face.
- 10" Hem. bears S9E 13 lks.; now 20" stump, partially exposed upper face, scribes $\frac{1}{4}$ visible.

RESTORED

Var. 21 $\frac{1}{2}$ E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ S17 S20 1964 RS401", 32 inches in ground, and from which a:

- 38" Hem. stump bears S76 $\frac{1}{2}$ E 34.0 ft.; scribed $\frac{1}{4}$ S20 BT RS401.
 - 18" Hem. snag bears N50W 153.6 ft.; scribed $\frac{1}{4}$ S17 BT.
- corner is 125' North of a road which bears S80E by N80W.

Set 4" x 4" x 60 white painted Cedar post 1.0 ft. N.E. of corner pipe. Oregon State Forestry Department metal location poster on 18" Hem. B.T. Also poster on 4 ft. x 70 ft. log on North edge of road 125.0 South

Dated August 14, 1964

Restored by Harold J. Russell under my direction.
Harold J. Russell, Transitman

Present and witnessed by W. Coblintz



Richard A. Morris

