


County Surveyor's Record, Tillamook County, Oregon

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

(Reference FSH 5681.65)

History of original corner establishment:

This corner was established in 1882 by the General Land Office. (William P. Wright, surveyor)
It was found in 1952 by W. A. Markham



Description of corner evidence found:

Found 1½ inch by 36 inch iron pipe for corner to Sections 16, 17, 20, 21 with 1½ inch by 24 inch iron pipe alongside from which:


- A hemlock snag, 22 inches in diameter bears N33½E, 11.2 feet distance
- A spruce, 27 inches in diameter bears S80¼E, 25.9 feet distance
- A fir, 47 inches in diameter bears S25 ¾ W, 66.9 feet distance
- A hemlock, 16 inches in diameter bears N2¼W, 48.4 feet distance

* See Book PAGE

Description of monument and accessories established to perpetuate the original location of this corner

At the corner point set a 2 inch by 30 inch cement filled iron pipe with a brass cap marked

T5S R10W



1968

ORLS 650

Deposited the two iron pipes beside the monument

Placed U.S.F.S. bearing tree signs on all BT's facing the monument.

Office of County Surveyor County of Tillamook
State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 1st day of August, 1968 at 2 o'clock p.m., (signed)
W. A. Markham by _____
(COUNTY OFFICIAL) (DEPUTY)

REGISTERED
OREGON
LAND SURVEYOR

Tom O. McCullough
JULY 10, 1964
TOM O. McCULLOUGH
650

BOOK 3