


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**History of original corner establishment:**

Corner established in 1880 by General Land Office.  
Surveyor: Samuel Caudle.

Original Survey states: Set a stone 12" x 8" x 6"  
and built mound of stone.

No bearing trees were set as timber had been destroyed  
by fire.



**Description of corner evidence found:**

Found a 3/4" iron rod and 3 Alder bearing trees with Oregon State Board of Forestry tags.


Bearing trees are as follows:

- A 14" Alder bears N 86° W 19.2 feet, bark scribed C.S., S23, B.T.
- A 22" Alder bears S 28° W 14.4 feet, bark scribed C.S., S26, B.T.
- A 14" Alder bears S 6°-E 28.0 feet, bark scribed C.S., S25, B.T.

**Description of monument and accessories I established to perpetuate the original location of this corner**

At the position of the 3/4" iron rod, I placed a galvanized iron pipe 30" long and 2" in diameter, with circular flange at bottom and capped with a brass disk welded to the top of the pipe. The monument projects 4" above the ground.

I stamped the disk →



From the pipe monument the bearing trees are as listed above in description of corner evidence found. An open field in Section 24 precludes setting a B.T. in that quadrant. A U.S.F.S. bearing tree sign was set on all B.T.'s.

Office of County Surveyor County of Tillamook  
 State of Oregon, I hereby certify that the within instrument was filed in this office  
 for record on the 29<sup>th</sup> day of JULY, 1970, at        o'clock        m., (signed)  
Samuel Caudle by County Surveyor  
 (COUNTY OFFICIAL) (DEPUTY)

