

County Surveyor's Record, Tillamook County, Oregon

CHAINS

Page 9

TOWNSHIP 6 SOUTH, RANGE 10 WEST

S 1/16 Corner, Sections 3/2, T6S, R10W

Found 1" galvanized iron pipe for corner.
Found 2 BT's previously recorded by U.S.F.S. in 1952.

2

I drove a 1 1/4" x 36" stainless steel pipe over the top of the 1" pipe.

Aspect - Flat - rolling.

Old Forest Service trail is 500' West bearing SE-NW.

Found by: Ray Thompson, LFCo.
Witnesses: R. McCollam, R. England,
Whitemore

September 9, 1970

Section Corner - Sections $\frac{3}{2}$, T6S, R10W
10/11

Found 1 1/4" stainless steel pipe for corner.

From which I found the following:

Rotted 18" Hemlock stub bears N 40° W 6.2 feet; fd. orig. scribe. 1

11" Hemlock bears N 80° E 7.1 feet; old face; prob. orig.

8" Spruce Snag bears S 56° E 7.2 feet; found scribe.

26" Spruce bears South 7.57 feet; fd. old cruiser marks; I added
screw nail, lead washer, and yellow tag only.

28" Hemlock bears S 47° W 15.3 feet; fd. yellow BT tag and old
cruiser initials, including "AR"

Corner sets on gentle west slope 400 feet north of road.

Found by: Russ Bass, LFCo.
Witness: Bob Mansfield

September, 1970

SE 1/16 Corner, Section 3, T6S, R10W

Set 1 1/4" x 36" stainless steel pipe for corner, established by LFCo.

Scribed the following BT's:

30" Hemlock bears N 45° W 26.8 feet; scribed "SE 1/16 S3 BT";
screw nail, lead washer, yellow tag.

36" Hemlock bears S 74° E 24.17 feet; scribed "SE 1/16 S3 BT";
screw nail, lead washer, yellow tag.

5

Scribed by: D. McCollam, LFCo.
Witnesses: R. Thompson, LFCo.
R. England, Ore-Wash Ply

September, 1970

BOOK 5

BOOK 5

109