

CHAINS  
CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Township corner common to Sections 1 and 36, T2&3N, R7W, W.M.,  
Washington and Tillamook Counties, Oregon.

ORIGINAL

Basalt stone 18" x 15" x 12" (in place) from which a:

- 15" Hemlock bears S32°E 75 lks.; missing.
- 12" Hemlock bears S22°W 60 lks.; missing.
- 48" Fir bears N30°W 31 lks.; missing.
- 36" Fir bears N89½°E 62 lks.; roothole in place.

RESTORATION by L. W. Amort, July 14, 1955.

Erected mound of rock around original stone (in place) from which a:

- 6" Fir bears S46°W 16 ft.; now an 8" snag with face grown over.
- 48" Fir stump bears N47°W 177.2 ft.; not looked for.
- 4" x 3" x 72" WPCP bears NE 1.0 ft.; in place.

RESTORED

Var 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON  
STATE BOARD OF FORESTRY T2 - 3N R6 - 7W S36 S1 S6 1974 RS 707," 30  
inches in ground, with original stone on North edge of corner pipe,  
in mound of rock, and from which a:

- 9" Hemlock bears N72°E 7.3 ft. to face; scribed T2N R6W S6 BT.
- 8" Fir bears N16½°W 7.7 ft. to face; scribed T3N R7W S36 BT.
- 10" Fir bears S15-¾°W 4.6 ft. to face; scribed T2N R7W S1 BT RS 707.
- 12" Fir bears S71½°E 21.9 ft. to face; scribed T2N R6W S6 BT.

Set 4" x 3" x 72" white painted Cedar post 1.0 ft. NE of corner pipe.  
Oregon State Forestry Department metal location poster on 10" Fir BT.

Dated December 16, 1974.

Restored by Loren Steele under my direction.  
Loren Steele, Forest Engineer

Present and witnessed by Terry Withrow

