

County Surveyor's Record, Tillamook County, Oregon  
County Surveyor's Record, Tillamook County, Oregon

CHAINS  
CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 8 and 9, T3N, R6W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 24" Fir bears S43 $\frac{1}{2}$ °E 98 lks.; now a 39" uproot, roots in place, face not exposed.
- 20" Fir bears S32°W 26 lks.; now a 24" uproot, scribes 1/4 S visible, point falls in cat road.

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R6W  $\frac{1}{4}$  S8 S9 1975 RS707", 32 inches in ground, in small mound of rock, and from which a:

Variation 21-1/2° E

- 14" Noble Fir bears S19°E 28.3 ft. to face; scribed  $\frac{1}{4}$  S9 BT.
- 13" Hemlock bears N52°W 18.0 ft. to face; scribed  $\frac{1}{4}$  S8 BT RS707.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. SE of corner pipe. Oregon State Forestry Department metal location poster on a 12" Hemlock N7°E 10.8'.

Dated October 6, 1975.

Restored by

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Harold J. Russell*

OREGON  
JULY 9, 1965  
HAROLD J. RUSSELL  
707

Present and witnessed by Loren Steele

BOOK 5