

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 23, 24, 25 and 26, T1N, R6W, W.M., Tillamook and Washington Counties, Oregon.

ORIGINAL

24" x 10" x 7" Stone, missing from which a:

10" Hemlock bears S27°W 47 lks.; now 9" burnt stub, 2' tall, axe work at bottom of face, scribes burnt away.

RESTORATION by Lyle E. Byers, OSBF in 1949

OSBF pipe and cap, missing torn out during road construction from which a:

42" Hemlock snag bears N23°W 27.1 ft.; now 40" stump, scribe visible, now 27.3 ft.

40" Fir stump bears S63°W 27.5 ft.; now S68°W 26.7 ft., scribe visible.

Note: Reset corner point from original BT.

RESTORED

Var. 21½° East

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1NR6W, S23 S24 S25 S26 1980 RS707", 24 inches in ground, in large mound of rock, and from which a:

9" Fir bears N47°E 62.36 ft. to face; scribed T1NR6W S24 BT.

9" Noble Fir bears S53 ¾°E 34.00 ft. to face; scribed T1NR6W S25 BT.

8" Fir bears S81°W 30.60 ft. to face; scribed T1NR6W S26 BT.

8" Fir bears N16½°W 11.83 ft. to face; scribed T1NR6W S23 BT RS707.

Cat road bears North 50.00 ft. course S42°E by same.

Set 4" x 4" x 60 white painted Cedar post 1.0 ft. West of corner pipe. Oregon State Forestry Department metal location poster on 8" Fir BT S81°W 11.83 ft.

Dated August 20, 1980

Restored by

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Harold J. Russell

OREGON
JULY 9, 1965
HAROLD J. RUSSELL
707

Present and witnessed by Charles Clay