

County Surveyor's Record, Tillamook County, Oregon

3/18/77
J.E.H.

Corner Report

Center 1/4 Section 30, T2S, R10W, W.M.
Tillamook County, Oregon

Restoration 4-20-66 by G. Arthur and S. Skinner:

Found old spruce limb with scribing "1/4 S" 12"⁺ high and a 1 1/2" iron pipe badly bent 1.5' Northerly of post. Old bearing trees fit post. 12" Hemlock stump N50°E 35.4', scribing still good 32" Hemlock N19°30'W 40.0', did not open. Set 2" iron pipe in place of old Spruce limb. Left Spruce limb beside pipe.

Parks Crew Found

1 1/2" iron pipe leaning but not bent. Steel post with Tillamook County Surveyor's tag 1.0' SE of pipe.

24" Hemlock stump 5' high N50 1/2°E 35.6' to center, "1/4 BT" visible. White paddle stenciled "Tillamook County bearing tree do not cut" nailed to stump.

40" Hemlock N19°W, 40.2' to face, 41.8' to center. Did not open.

Looked for 2" pipe described above but could not find.

Used 1 1/2" iron pipe where it entered the ground since the bearing trees did not fit too badly.

Set steel post with paddle marked, "OREGON STATE PARK BOUNDARY do not disturb" 2' West of pipe.

See map A-3120