


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

*SEE MAP B-970  
FOR RESET OF THIS  
CORNER  
4/13/81  
Allan Duncan C.S.*

Description of monument and accessories established to perpetuate the original location of this corner:

At proportionate measurement I set a 2 1/2" X 30" galvanized iron pipe with a flared bottom and a brasscap riveted to the top marked:

T 4 S	R 8 W	From Which,
S2		18" Alder N 56° E, 9.8 feet
NE-SE		mkd "NE-SE 1/64 S 2" "B.T." Bark Scribed
1/64		39" D. Fir S 15° E, 23.0 feet
1977		mkd "NE-SE 1/64 S 2" "B.T."
RLS 1073		

Set 6' steel fence posts with property boundary and Land Survey signs. All bearing trees have brass washers, attention signs, bearing tree tags and painted bands.

Witness: Ed Tatro

*See Map B-764*

D. Mike Jackson  
Engineering Technician

Office of... County Surveyor ... County of TILLAMOOK  
State of OREGON ... I hereby certify that the within instrument was filed in this office  
for record on the 24 day of AUGUST ... 1977

[Signature]  
(COUNTY OFFICIAL)

by County Surveyor  
(DEPUTY)

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Kenneth M. Wightman  
OREGON  
JULY 17, 1970  
KENNETH M. WIGHTMAN II  
942

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR  
GPO-798-276

Edgar R. Cook  
OREGON  
JULY 30, 1975  
EDGAR R. COOK  
1073

Form R6-7100-57 (9/71)

*Book 6*

*pg 33*



TIMBERLAND SERVICES, INC.  
1010 Airport Blvd. P. O. Box 558  
Astoria, Oregon 97101  
Telephone (503) 326-9904  
LAND SURVEYING - ENGINEERING  
LAND USE PLANNING - ROADS  
FORESTRY CONSULTING