

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 4 and 5, T3S, R7W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

12" Cedar bears N49°E 43 lks.; now a 30" snag, pushed out of place by a cat, found axe work.

6" Vine maple bears S56°W 29 lks.; missing.

RESTORATION by L. W. Amort, June 7, 1952

1 1/2" x 36" galvanized iron pipe with 3" bronze cap 30" in ground, (in place) from which a:

41" Fir snag bears N75°E 83.9 ft.; now 45" stump, with 1/4 S4 BT visible.

44" Fir stub bears N41°W 16.5 ft.; now 37" stump, with 1/4 S5 BT RS2311 visible.

REWITNESSED

Var. 21 1/2° East

From above 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S4 S5 1952 2311," 34 inches in ground a:

21" Fir bears S09°E 12.7 ft. to face; scribed 1/4 S4 BT RS 707.

15" Fir bears S82°W 36.7 ft. to face; scribed 1/4 S5 BT.

Oregon State Forestry Department metal location poster on 21" Fir BT.

Dated May 29, 1980

REWITNESSED by Anthony J. Klosterman under my direction.
Anthony J. Klosterman, District Engineer

Present and witnessed by Dave Buchholz
Danny Benson

