

OREGON STATE PARKS AND RECREATION DIVISION

RESURVEY
OSWALD WEST STATE PARK
Section 17, T3N, R10W, W.M.
Tillamook County, Oregon
May 1, 1981

SURVEY NARRATIVE

This resurvey was made necessary for a couple of reasons. The State, in its transactions with Crown Zellerbach, disposed of property in the Northeast and Southeast quarters of the Northeast quarter of Section 17. The Highway Division, in cleaning out their Engineering office in Astoria, found a collection of survey notes which were given to the Tillamook County surveyor. These notes, by virtue of a highway tie, enabled the county surveyor to locate the quarter corner between Section 17 and Section 20 in T3N, R10W. These same notes enabled the State Park survey crew via a highway tie to locate the witness corner to the quarter corner common to Sections 16 and 17.

Much of the control information from the 1975 survey was used for this survey. The new control was tied using a McHenry 2H electronic distance measuring instrument and a Jena one-minute theodolite. The bearing was taken from a solar observation made for the 1975 survey.

CORNER INFORMATION

Magnetic Variation $20\frac{1}{2}^{\circ}$

Section Corner Sections 7, 8, 17 and 18 (1975)

Found corner stump and $\frac{1}{2}$ " iron pipe bearing S40⁰W, 3.2' from corner stump.

- 52" Hemlock N23 $\frac{1}{2}$ ⁰W, 66.0', scribed "T3N R10W S7 BT RS 707".
- 14" Hemlock N34 $\frac{1}{2}$ ⁰E, 46', scribed "T3N R10W S8 BT".
- 19" Hemlock stump S24⁰W, 32.1', scribed "T3N R10W S18 BT".
- 27" Hemlock stump S79⁰E, 47.5', scribed "T3N R10W S17 BT".

$\frac{1}{2}$ Corner Sections 8 and 17 (1975)

Found 2" iron pipe 1.5' above ground.

- 29" Hemlock stump 4' high S29⁰E, 7.6' to center, cut off tree lies South of stump with undefined traces of scribe and corner tag that states "Cor Set By Compass and Chaining".
- 6" Hemlock with scars but no visible scribing N25 $\frac{1}{2}$ ⁰W, 4.4' to center and rotted out stump directly behind.
- 7" Spruce stump 8' high N7⁰W, 26' with "TTC" chopped on SE side.

E1/16 Corner Sections 8 and 17 (1975)

Set headless conc. nail in a conglomerate stone exposed 3'x3 $\frac{1}{2}$ 'x2' high. A chisled arrow in the rock points to nail.

- 8" Spruce N47⁰W, 9.8', marked with an "X".
- 6" Spruce N16⁰E, 3.3', scribed "E1/16 S8 BT".
- 8" Hemlock with Parks corner tag S35 $\frac{1}{2}$ ⁰W, 11.7', scribed "E1/16 S17 BT RS-691".

Set steel post with boundary paddle.

Section Corner Sections 8, 9, 17 and 16 (1975)

Found 1" iron pipe 1' above ground; a downed 34" Cedar N20⁰W, approximately 12' to original position, with chop marks and what appears to be a back cast of an old blaze in the chop marks, and undefined initials chopped in bark; a rotted out stump N53⁰E, 23.4'; a rotted out stump S8⁰E, 12.5'.

Set (1975) 5/8"x30" capped iron rod inside 1" pipe and 0.3' above top of pipe, steel post with boundary paddle.