

County Surveyor's Record, Tillamook County, Oregon

CHAINS

REWITNESSED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Witness corner common to Sections 22, 23, 26, and 27, T3N, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 58" Hemlock bears N60°E 26 lks.; now missing.
- 24" Hemlock bears S42°E 35 lks.; now 24" badly rotted stump, face rotted away.
- 40" Hemlock bears S51°W 15 lks.; now 50" stump scribes 3NR8 visible.
- 36" Hemlock bears N18°W 32 lks.; now 24" badly broken stump, scribes T3NR8WS2 visible.

RESTORATION By Louis W. Amort, April 8, 1952.

1½" X 36" galvanized iron pipe with 3" bronze cap 30" in ground, in mound of rock, 5 feet south of corner point, (in place) from which a:

32" Fir stump bears N67°30'E 76.7 feet.; now 30" stump, portions of scribes 3 & S2 BT2311 visible.

REWITNESSED

Var. 21½°E

From above 1½" X 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY WC T3NR8WS22 S23 S27 S26 5FT N 1952 2311", added marks 1981 RS1662, 30 inches in ground, in mound of rock, and from which a:



- 9" Fir bears S61°W 38.8 ft. to face; scribed T3NR8WS27BTRS1662.
- 9" Spruce bears S11°30'E 14.0 ft. to face; scribed T3NR8WS26BT
- 9" Alder bears N57°E 64.3 ft. to face; bark scribed T3NR8WS23BT.
- 12" Hemlock bears N38°W 74.8 ft. to face; scribed T3NR8WS22BT.
- Center line of Brix Incline Road bears North 15.0 ft., course East-West.

4" X 4" X 60" white painted Cedar post SE 1.0 ft. from corner pipe. Oregon State Forestry Department metal location poster on original 40" Hemlock BT.

Dated September 8, 1981.

Restored by David Buchholz under my direction.

David Buchholz, Transitman



Present and witnessed by Danny Benson.

rock