

# County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 14 and 15, T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL by C.J. Handley, July 8, 1873.

Post in mound (missing) from which a:

5" Hemlock bears S80°E 21 lks.; now missing.  
36" Hemlock bears S25°W 12 lks.; in place, badly rotted, no scribing visible.

NOTE: Horizontal distances fit well when measured from the approximate face of BTs.

RESTORATION by R.R. Hayes, August 25, 1887. (Book 1 pg 12, Tillamook County records)

Post (missing) from which a:

8" Hemlock bears S62°E 21 lks.; missing.  
38" Hemlock bears S22°W 13 lks.; in place, original BT, see above.

RESTORATION by unknown (unrecorded).

3/4" iron bolt from which a:

31" Hemlock stump bears N68°E 29.3 ft.; scribes 1/ visible on rotted face.

RESTORED

Var. 21½°E


Set 1½" X 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1N R10W 1/4 S15 S14 1984 RS1998", 33 inches in ground, over 3/4" iron bolt and from which a:

15" Hemlock bears S35°E 29.9 ft. to face; scribed 1/4S14BT.  
12" Hemlock bears N79°W 7.2 ft. to face; scribed 1/4S15BT.


Set 4X4X60" white painted Cedar post S45°W 0.6 ft. from corner pipe. Oregon State Forestry Department metal location poster on 21" Hemlock stump N58°E 31.2'.  
Also posters on new BTs.

Dated July 26, 1984

Restored by:



*Anthony J. Klosterman*



Present and witnessed by David B. Buchholz  
Clifford Foster