

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner ( common to) Sections 20,21,28 and 29, T3N, R7W, W.M.,  
Tillamook County, Oregon.

ORIGINAL

18"x8"x6" Basalt stone (missing) from which a:

- 18" Fir bears N60°E 30lks,; missing.
- 6" Hemlock bears S29°E 21 lks,; missing.
- 5" Maple bears S59°W 24 lks,; missing.
- 18" Hemlock bears N70°W 48 lks,; missing.
- 10 link creek; Crs. N80°E; bears South 14.6 chains; in place.
- Salmonberry River; Crs. N20°W; bears East 13.77 chains; in place.
- Top of spur bears North 3 chains, slopes NE; in place.
- 60" Fir line tree bears West 1.29 chains; in place.
- Top of spur; Crs. N60°E; bears West 3 chains; in place.

RESTORED

VAR 21½°E

Set 2"x36" aluminum pipe with 3 3/4" aluminum cap marked "STATE OF  
OREGON DEPARTMENT OF FORESTRY T3N R7W S20 S21 S28 S29 1985 RS1662",  
34 inches in ground, and from which a:

- 9" Alder bears N42°W 0.5 ft. to face; bark scribed T3NR7WS20BT.
- 9" Fir bears N10°E 34.8 ft. to face; scribed T3NR7WS21BT.
- 8" Alder bears S51°W 36.0 ft. to face; bark scribed T3NR7WS29BT.
- 27" Fir bears S12°E 44.3 ft. to face; scribed T3NR7WS28BT.

Set 4"x4"x60" white painted Cedar post SW 1.0 ft. from corner pipe.  
Oregon State Forestry Department metal location poster on 9" Alder BT.

Dated August 13, 1985

Restored by:



Present and witnessed by: S. Ellis  
O. Hendrick