

RESTORED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY  
4907 Third St., Tillamook, Oregon 97141

One quarter corner common to Sections 5 and 6, T2N, R7W, W.M.,  
Tillamook County, Oregon.

ORIGINAL by Henry Meldrum, August 2, 1893.

15"x11"x9" basalt stone 10" in ground; in place, marks 1/4 visible.

6" Hemlock bears S86W 58 lks.; missing.  
16" Hemlock bears N85E 36 lks.; now a 12" x 3 ft. high badly rotted  
stub with axe work and portion of scribe visible on portion of  
burnt face.

REWITNESSED by Louis W. Amort RE2311, November 16, 1955 (Book 2,  
page 328, Tillamook County Records).

Erected mound of stone around corner stone; in place.

46" Fir stump bears N81E 19.2 ft.; now a 46" x 4 ft. high rotted  
stump with scribes 1/4 S5 BT visible.  
47" Fir snag bears N67W 20.0 ft.; now a 47" x 4 ft. high stump  
with scribes 1/4 S6 BT RE2311 visible.  
4"x4"x72" white painted Cedar post 2 ft. NE of corner; found a  
2"x4"x50" high post, in place.

RESTORATION September 4, 1990

Var. 21 1/2 E

Set a 1 1/2"x30" Aluminum pipe with 3 3/4" cap marked "STATE OF OREGON  
DEPARTMENT OF FORESTRY T2N R7W 1/4 S6 S5 1990 LS1998, 28" in ground,  
in mound of stone, original corner stone placed at NE edge of pipe,  
and from which a:

17" Fir bears S54E 38.4 ft. to face; scribed 1/4S5BT.  
19" Fir bears N62 1/2W 14.25 ft. to face; scribed 1/4S6BT.

Metal location poster on new BTs.

Also 1955 poster on 46" Fir BT.

3/4" brass washer marked "LS1998" nailed to face of new BTs.

Present and witnessed by Carl J. Walter.

Restored by David B. Buchholz under my direction.  
David B. Buchholz, LS2272

