

RESTORED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY
4907 Third St., Tillamook, Oregon 97141

One quarter corner common to Sections 31 and 36, T2N, R7&8W, W.M.,
Tillamook County, Oregon.

ORIGINAL by Henry Meldrum, August 13, 1891.

15"x10"x7" basalt stone; missing.

36" Hemlock bears N55W 10 lks.; missing.

48" Fir bears N58E 27 lks.; now a 22" x 5 ft. high badly rotted
stump with no scribes visible.

RESTORATION by Louis W. Amort RE2311, June 7, 1952 (Book 2, page 219,
Tillamook County Records).

1 1/2" x 36" Galvanized iron pipe with 3" bronze cap 2 1/2 ft. in
ground, in mound of stone, 5.0 ft. North of true corner point; in
place.

45" Fir snag bears N25E 22.4 ft.; now a 5 ft. high stump with
scribes WC 1/4 S31 BT RE2311 and four cruisers marks visible.

27" Fir snag 20 ft. high bears S21W 27.3 ft.; now an 18" x 4 ft.
high badly rotted stump with scribes W 1/4 BT laying
alongside.

Metal location poster on a 42" Fir snag bears S31W 12.7 ft.; now
a 7 ft. high badly rotted stump with poster missing.

RESTORATION October 22, 1990

Var. 21 1/2 E

Marked above pipe "RM" and drove flush with ground, from which I set
a 1 1/2" x 30" Aluminum pipe with 3 3/4" cap marked "STATE OF OREGON
DEPARTMENT OF FORESTRY T2N R8W R7W 1/4 S36 S31 1990 LS1998, 29" in
ground, 5.0 ft. South of witness corner at true corner point, from
which a:

10" Fir bears N43 1/2E 12.8 ft. to face; scribed 1/4S31BT.

11" Fir bears N82W 13.7 ft. to face; scribed 1/4S36BT.

Metal location poster on new BTs.

3/4" brass washer marked "LS1998" nailed to face of new BTs.

Present and witnessed by David B. Buchholz and Clifford R. Foster.

Restored by

