

RESTORED CORNER THE OREGON DEPARTMENT OF FORESTRY

Standard section corner common to Sections 33 and 34, T1N, R8W,  
W.M., Tillamook County, Oregon.

ORIGINAL by Samuel D. Snowden, September 16, 1856.

Post; missing.

- 72" Fir bears N35E 30 lks.; now a 74" x 6 ft. high stump with no scribes visible.
- 32" Hemlock bears S14E 20 lks.; now a 40" badly rotted stump with scribes R8M T1S S3 visible. (W is upside down).
- 10" Hemlock bears S86W 16 lks.; missing, point falls on cutbank of old cat road.
- 8" Hemlock bears N23W 57 lks.; missing, point falls in old cat road.

RESTORATION by Henry Meldrum, August 8, 1884.

Post; missing.

RESTORATION by Louis W. Amort RE2311, November 25, 1952 (Book 2, page 233, Tillamook County Records).

1 1/2"x36" galvanized iron pipe with 3" bronze cap, 30" in ground, in mound of stone; found, out of place.

- 8" Alder bears N15W 61.8 ft.; now 18" with no scribes visible on partially open face.
- 60" Fir snag bears N57 3/4E 81.2 ft.; now a 60" x 8 ft; high stump with faint scribes visible.
- Metal location poster on Original 72" Fir; found, laying on ground next to stump.

RESTORED DECEMBER 16, 1991

Var. 19 1/2 E

Reset the above pipe 34" in ground with marks "LS1998 1991" added, and from which a:

- 74" Fir stump (1856) bears N40E 19.8 ft. to face; scribed T1NR8WS34SCBT.
- 14" Alder bears N64W 53.7 ft. to barkscribes T1NR8WS33SCBT.

Metal location poster on new BTs, and 1952 Alder BT.  
3/4" brass washer marked "LS1998" nailed to face of new Fir BT.  
Present and witnessed by David B. Buchholz and Clifford R. Foster.

Restored by

