

TILLAMOOK COUNTY SURVEYORS OFFICE  
COURT HOUSE, TILLAMOOK, OREGON 97141

CN 1/16 CORNER SECTION 23, T.1N., R.10W., W.M.

C  
1 | I found a 1 1/2" iron pipe with a 3" Oregon State  
N / + S 23 Board of Forestry Bronze Cap, (see T.C.S. Map  
16 | #B-419), bent, I straightened and reset in vertical  
C portion of hole. I added "CS RESET 1992" to the cap  
CS RESET 1992 and encased the found Iron Pipe and Bronze Cap in a  
1959 10" concrete cylinder.  
RS 401

-----  
History of found monument

I found this monument to be as described on said T.C.S. Map and the references found and/or set at that time to now be as follows:

(Map #B-419) 29" fir N.8°W. 16.5'; (Found, now a 27" rotten stump 6' high, face rotted off).

(Map #B-419) 28" hemlock S.76°E. 17.6'; (Found, now a rotten stump 2' high, face portion ripped off by cat blade).

Found white cedar post rotted off and laying alongside of corner position.

-----  
New Accessory

\*72" light hat section post North 1.4'.

\*7" Spruce N.18°W. 8.52', scribed "CN1/16S23BT". The distance was measured to a nail with brass washer in the face between the B & T.

\*12" Hemlock N.85°E. 30.25', scribed "CN1/16S23BT". The distance was measured to a nail with brass washer in the face between the B & T.

\*indicates Tillamook County Surveyors yellow metal location poster attached.

-----  
Surveys and Rewitnesses of record

B-419	12-31-59	Richard A. Morris	RS 401
Rewitness Book 2 page 431	12-31-59	Richard A Morris	RS 401
B-901	Apr. 1980	C. Wayne Cook	LS 1098

-----  
Location of Monument

This corner is located approximately 50' Southerly of a gravel logging road on the West side of a cat road.

-----  
In the presence of Al Dvorak and Dan McNutt

May 14, 1992

Title

