

REWITNESSED CORNER FOR OREGON DEPARTMENT OF FORESTRY  
4907 Third St., Tillamook, Oregon 97141

Section corner common to Sections 20, 21, 28 and 29, T1N, R7W,  
W.M., Tillamook County, Oregon.

ORIGINAL by Henry Meldrum, September 21, 1884.

Post; missing.

- 4" Vine Maple bears N37W 83 lks.; missing.
- 16" Hemlock bears N65E 29 lks.; now a badly rotted root crown with no scribes visible.
- 12" Hemlock bears S46E 40 lks.; now a 12" badly rotted windfall with no scribes visible.
- 28" Fir bears S59W 19 lks.; now a 43" x 7 ft. high badly rotted stump with scribes BT visible on burnt face, bears S57W 12.44 ft. to face.

RESTORATION by Lyle E. Beyers LS199, March 1, 1951 (Book 2, page 65-B, Tillamook County Records).

- 1 1/2"x36" galvanized iron pipe with 3" bronze cap; now 28" in ground and firmly set, leaning slightly to the West;
- 41" Fir snag bears S30E 29.5 ft.; now a 47" x 7 ft. high rotted stump with scribes 8 BT 199 visible.

REWITNESSED September 16, 1992

Var. 19 1/2E

From above pipe with marks "LS1998 1992" added a:

- 24" Fir bears N20 1/2E 18.6 ft. to face; scribed T1NR7WS21BT.
- 10" Fir bears S71 3/4E 10.6 ft. to face; scribed T1NR7WS28BT.
- 9" Fir bears S21 1/2W 27.0 ft. to face; scribed T1NR7WS29BT.
- 22" Fir bears N43W 23.6 ft. to face; scribed T1NR7WS20BT.

Metal location poster on new BTs.

Also 1951 metal location poster on Original 28" Fir BT.

3/4" brass washer marked "LS1998" nailed to face of new BTs.

Present and witnessed by Clifford R. Foster.

Rewitnessed by David B. Buchholz under my direction.  
David B. Buchholz, LS2272

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Anthony J. Klosterman*  
OREGON  
JULY 16, 1982  
ANTHONY J. KLOSTERMAN  
1998

