

TILLAMOOK COUNTY SURVEYORS OFFICE
TILLAMOOK COUNTY COURT HOUSE
201 LAUREL AVENUE
TILLAMOOK, OREGON 97141

1/4 CORNER COMMON SECTIONS 13 & 24 T.2S., R.10W., W.M.

1 S13 I found a 2" iron pipe with a 3" Tillamook County
/ ---+--- Surveyors Brass Cap (see T.C.S. Rewitness Card
4 S24 #457.
RS 287
1978

History of found monument

I found this monument to be as described in T.C.S. Rewitness Card #457 and the references found and/or set at that time to now be as follows:

(Book 4 Page 93) 24" Hemlock S.88°E. 11.1', reported on above rewitness as a found 30" snag 25' high scribing visible, 15.1'; (Now very rotten snag, top has fallen over, scribing is visible on very rotten face, 15.1').

(Book 4 Page 93) 18" Hemlock S.26°15'W. 15.1', reported in above rewitness as a 40" stump, scribing visible, 11.1'; (Found, now a 40" hemlock stump 11.1' to approximate rotted out face).

*(Rewitness Card #457) 6" Hemlock N.18°W. 9.41'; (Found, now a 15" Hemlock, face healed over).

*(Rewitness Card #457) 12" Hemlock S.48°E. 28.75'; (Found, now a 17" Hemlock, face partially healed over, scribing visible).

Found 4"X 4"X 60" post rotted and laying alongside of monument.

New Accessory

*72" light hat section post North 1.5'.

*indicates Tillamook County Surveyors yellow metal location poster attached.

Surveys and Rewitnesses of Record not listed on Rewitness Card #457

B-922	7-31-80	Robert J. Olsen	LS 701
AMA Field Notebook 8 at page 150	1901	A.M. Austin	
Rewitness Card #457	10-25-78	John L. Carllich	RS 287

Location of Monument

This corner is located approximately 225' South of an old logging road, which has recently been cleared out. I attached a Tillamook County Yellow Location Poster on a 15" hemlock approximately 225' North of the corner on the South side of the road.

In the presence of Al Dvorak and Dan McNutt

August 17, 1992

Title

