

REWITNESSED CORNER OREGON DEPARTMENT OF FORESTRY
4907 Third St., Tillamook, Oregon 97141

One quarter corner common to Sections 14 and 15, T1S, R7W, W.M.,
Tillamook County, Oregon.

ORIGINAL by Albert P. Wilson, October 12, 1891.
Post; missing.

32" Hemlock bears S70E 5 lks.; now a 30" x 9 ft. high badly
rotted stub with no scribes visible, bears S59E 4.9 ft.
to center.

28" Hemlock bears N57W 26 lks.; missing.

RESTORATION by Louis W. Amort RE2311, April 1, 1954 (Book 1,
page 118, Tillamook Co. Records.)

1 1/2"x36" galvanized iron pipe with 3" bronze cap, 33" in
ground, in mound of stone; now 38" in ground, in place, on
top of spur ridge which slopes N72E.

3" Fir bears S77 1/2W 117.8 ft.; missing.

48" Fir snag bears S12E 42.9 ft.; now 30 ft. high and
rotted with scribes 1/4 S14 BT RE2311 and cruisers mark
visible.

4"x4"x72" white painted Cedar post 1.0 ft. NW of pipe; in
place.

REWITNESSED September 22, 1992

Var. 19 1/2 E

From above pipe with marks "LS1998 1992" added, a:

17" Fir bears N13 1/2E 30.1 ft. to face; scribed 1/4S14BT.

11" Fir bears S78 1/2E 27.5 ft. to face; scribed 1/4S14BT.

17" Fir bears S39 1/2W 30.8 ft. to face; scribed 1/4S15BT.

15" Fir bears N71W 41.6 ft. to face; scribed 1/4S15BT.

Metal location poster on new BTs.

Also 1954 metal location poster on Amort's 48" Fir snag BT.
3/4" brass washer marked "LS1998" nailed to face of new BTs.
Present and witnessed by Clifford R. Foster.

Rewitnessed by David B. Buchholz under my direction.
David B. Buchholz, LS2272

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Anthony J. Klosterman
OREGON
JULY 16, 1982
ANTHONY J. KLOSTERMAN
1998

