

RESTORED CORNER FOR OREGON DEPARTMENT OF FORESTRY
4907 Third St., Tillamook, Oregon 97141

Section corner common to Sections 22, 23, 26 and 27, T2N, R7W,
W.M., Tillamook County, Oregon.

ORIGINAL by Henry Meldrum, September 8, 1891.

Post; missing, point falls in rock slide.

- 18" Fir bears N81E 54 lks.; now a 24"x50 ft. high rotted snag with portions of scribes visible on burnt face.
- 8" Hemlock bears S29E 77 lks.; missing, point fall in old cat road, course S87W by N87E.
- 36" Fir bears S54W 51 lks.; now a 34"x25 ft. high rotted snag with axe work visible on burnt out face.
- 42" Fir bears N28W 22 lks.; missing, point falls in rock slide.

NOTE: Distances measured to face of BTs.

RESTORATION by Lyle E. Byers LS199, February 19, 1951 (Book 2, page 66, Tillamook County Records).

1 1/2"x36" galvanized iron pipe with 3" bronze cap; found dislodged by rock slide.

- 30" Fir snag bears N15E 39.3 ft.; now 36.9 ft. to a 37"x3 ft. high rotted stump with scribes S23 199 BT visible.
- 36" Fir snag bears S85E 37.5 ft.; now a 15 ft. high rotted snag with scribes S26 199 BT visible, which bears S76E 34.75 ft.
- 54" Fir snag bears S83W 43.9 ft.; now 42.2 to a 4 ft. high rotted stump with scribes T2N R7W S27 199 BT visible.

NOTE: Distances measured to face of BTs.

RESTORED December 23, 1992

Var. 19 1/2 E



Reset above pipe with marks "1992 LS1998" added, 35" in ground from original BTs and from which a:

- 26" Fir bears N55E 37.9 ft. to face; scribed T2NR7WS23BT.
- 14" Fir bears S52E 44.05 ft. to face; scribed T2NR7WS26BT.
- 21" Fir bears N58W 56.1 ft. to face; scribed T2NR7WS22BT.

Metal location poster on new BTs.

Also 1951 metal location poster on Beyer's 36" Fir snag BT.
3/4" brass washer marked "LS1998" nailed to face of new BTs.
6 foot Carsonite post bears NW 1.0 ft. from pipe.
Present and witnessed by Clifford R. Foster.

Rewitnessed by David B. Buchholz under my direction.
David B. Buchholz, LS2272



Expires 12/31/93