

REWITNESSED CORNER FOR OREGON DEPARTMENT OF FORESTRY  
4907 Third St., Tillamook, Oregon 97141

One quarter corner common to Sections 29 and 30, T3N, R7W, W.M.,  
Tillamook County, Oregon.

ORIGINAL by Henry Meldrum, December 10, 1891

Post; missing.

6" Hemlock bears N38½°E 45 lks.; missing.  
25" Hemlock bears S71°W 13 lks.; now a 20" x 15 ft. rotted  
off stub with root collar in place with no scribes  
visible.

RESTORATION by Richard A. Morris, LS401, August 4, 1959 (Book 1,  
page 368, Tillamook County Records).

1 1/2"x36" galvanized iron pipe with 3" bronze cap, 34" in  
ground, in small mound of stone; in place.

33" Fir stump bears N11½°E 40.5 ft.; now 2½ ft. high and  
badly rotted with portions of scribes 1/4 S29 BT  
visible.

44" Fir stump bears S51°W 5.0 ft.; now 5 ft. high and rotted  
with scribes 1/4 S30 BT RS401 visible.

Metal location poster on 38" Fir snag N09°W 34.6 ft.; in  
place, now 25 ft. high.

4"x4"x48" white painted cedar post 1.0 ft. NW of pipe; in  
place.

Top of spur, slopes West bears N00°05'W .5 chains; in  
place.

REWITNESSED January 11, 1999 Var. 19½°E  
From above pipe with marks "LS1998-1999" added a:

14" Fir bears N49°E 20.91 ft. to face; scribed 1/4S29BT.  
12" Fir bears S13°E 8.15 ft. to face; scribed 1/4S29BT.  
28" Fir bears S74°W 23.8 ft. to face; scribed 1/4S30BT.  
20" Fir bears N38½°W 14.95 ft. to face; scribed 1/4S30BT.


Metal location poster on new BTs.

3/4" brass washer marked "LS1998" nailed to face of new BTs.

6 ft. Orange carsonite post bears N89°E 2.05 ft.

Present and witnessed by Clifford R. Foster, David W. Wells and  
Colleen R. Holmen.

Restored by David B. Buchholz under my direction.  
David B. Buchholz, LS2272



SURVEYED BY:

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Anthony J. Klosterman*

OREGON  
July 21, 1982  
Anthony J. Klosterman  
1998

4907 THIRD STREET  
TILLAMOOK, OR 97141  
EXPIRES JUNE 30, 1999