

# BAYSIDE SURVEYING

11765 HWY 101 South  
Tillamook, Oregon 97141

Terry L. Jones  
503-842-5551  
Fax 503-842-5552

April 2002

## REWITNESS

SECTION CORNER COMMON TO SECTIONS 21, 22, 28 & 27  
TOWNSHIP 2 SOUTH, RANGE 8 WEST

I found:

OSBF brass cap on 1½" iron pipe stamped "T2S R8W S21 S22 + S28 S27 1966 RS 707", in stone mound, on steep SE slope. (See MAP B-531.)

54" Fir stump scribed "T2S R8W S27 BT" bears S6¼°E 19.0'. (54" Fir stump bears S6¼°E 19.0'. See MAP B-531.)

78" Fir stump scribed "T2S R8W S28 BT RS 707" bears S55¾°W 69.1'. (78" Fir stump bears S55¾°W 69.1'. See MAP B-531.)

½ shell of a 72" Fir stump scribed "T2S R8W S22 BT" bears N55°E 45.3'. (72" Fir stump (Hollow Shell) bears N55°E 45.3'. See MAP B-531.)

BPA tower bears S84°W 323'

---

I Set:

orange carsonite post 4' North, and 4 New BTs as follows:

18" Douglas Fir scribed "S22 BT" bears N33°E 41.60' to brass nail & washer stamped "LS 2507" between the B & T;

21" Douglas Fir scribed "S27 BT" bears S52°E 29.30' to brass nail & washer stamped "LS 2507" between the B & T;

19" Douglas Fir scribed "S28 BT" bears S38°W 25.80' to brass nail & washer stamped "LS 2507" between the B & T;

22" Douglas Fir scribed "S21 BT" bears N58°W 20.50' to brass nail & washer stamped "LS 2507" between the B & T;

In the presence of Terry Jones, Dallas Esplin

