


OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: The SE ¼ NE¼ of Section 25	TOWNSHIP 1 South	RANGE 10 West	
COUNTY: Tillamook		DATE: 09-01-06	
CORNER DESIGNATION: Centerline – Centerline monument at First Street and Stillwell Avenue in the city of Tillamook.		(Please check one)	
		<input type="checkbox"/>	Condition Report Only
		<input type="checkbox"/>	Not Found
		<input checked="" type="checkbox"/>	Renewed
		<input type="checkbox"/>	Unrecorded
		<input type="checkbox"/>	Surveyed In
		<input checked="" type="checkbox"/>	Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc.: Maps A-3811, A-4386, A-5078, A-5499, A-5810, A-6449, B-2582, Tillamook County Survey Records.			
Found Monument(s) and Accessories (Condition & Source): We first established a position by using the existing centerline monumentation at Third Street and Stillwell Avenue and at Seventh Street and Stillwell Avenue. We then used the control established by C. Wayne Cook, PLS 1098 and used a mean of the two angles to Cook's position and the position established by using the existing centerline monumentation. The mean of the angle right is 324° 35' 47".			
Monument Set (Procedures and Description): The reference markers set by the Tillamook County Surveyor for this centerline-centerline monument were removed by construction of a new sewer manhole. The control for a previous tie to the monument by C. Wayne Cook, PLS 1098 was used to re-establish the position of the monument. The occupy point is a found 'PK' nail in the sidewalk at the Southeast quadrant of the intersection of First Street and Stillwell Avenue. The back sight point is a found 30d nail in the sidewalk on the West side of Stillwell Avenue. The values being North 13° 08' 47" West 215.01'. The bearing and distance to the monument position from the 'PK' nail are North 48° 34' 48" West 46.74'. A 2" diameter Tillamook County brass disk, stamped as shown hereon, was then set at the road surface.		Sketch of Set Monument: 	
Other new accessories set: No other accessories were set.			
New Bearing Trees: No bearing trees were set.			
Location & Comments:			
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE		SURVEYOR'S SEAL <div style="border: 1px solid black; padding: 5px; display: inline-block;">REGISTERED PROFESSIONAL LAND SURVEYOR</div> <i>Danny R. McNutt</i> <div style="border: 1px solid black; padding: 5px; display: inline-block;">OREGON JULY 11, 2000 DANNY R. MCNUTT 49230</div> RENEWAL 12-31-2006	
Party Chief: Joe Jensen, Survey Supervisor			
Notes:			
Witness: Danny R. McNutt, Tillamook County Surveyor			

