

OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 19	TOWNSHIP: 3 South	RANGE: 9 West
COUNTY: Tillamook		DATE: 9/6/2007
CORNER DESIGNATION: Northwest 1/16 corner of Sec.19 Corner is on a steep NW slope 30 feet East of small creek, under large old fir stump.		(Please Check One)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Not Found
		<input type="checkbox"/> Reset
		<input type="checkbox"/> Referenced Out
Previous Rewitnesses, Restorations, Surveys, etc.: Map B-830		
Found Monument(s) and Accessories(Condition & Source): Found USFS aluminum cap with steel post with white sign 1.7 feet West and orange carsonite post 3 feet East with yellow signs. Also found 40" (38) hemlock high stump with partly healed face bears (N 67 W 76.7') and 48"(46") fir high stump with partly healed face bears (N89E 38.7').		
Monument Set(Procedures & Description): Monument in good condition		T3S R9W NW 1/16 S19 1979 PLS 896
Other New Accessories Set: Set second Steel Post 3 Feet North Also attached yellow "GREEN DIAMOND" property line tag on the post, painted top red and hung orange flagging.		
New Bearing Trees: Marked 2 new bearing trees as indicated 10" fir scribed "NW1/16S19B T" on low face with brass nail and washer marked "LS 2507" between the B & T bears South 31 East 21.62 feet. 16" hemlock (South tree of three) scribed "NW1/16S19B T" on low face with brass nail and washer marked "LS 2507" between the B & T bears North 81 East 20.70 feet.		
		Surveyor's Stamp
Firm/Agency: Bayside Surveying		
Address: 11765 Hwy. 101 South Tillamook, OR 97141		
Party Chief: Terry L. Jones		
Notes: in 3S 9 19 file in office		
Witness(es): Dallis Esplin Anthony Wright		Office Use Only

