

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

| | | |
|---|----------------------------------|--|
| SECTION: Southeast corner Section 20 | TOWNSHIP 1 South | RANGE 7 West |
| COUNTY: Tillamook | | DATE: 10-03-07 |
| CORNER DESIGNATION: The section corner common to Sections 20, 21, 29, 28, Township 1 South, Range 7 West, W.M., Tillamook County, Oregon. | | (Please check one) |
| | | <input checked="" type="checkbox"/> Condition Report Only |
| | | <input type="checkbox"/> Restoration |
| | | <input type="checkbox"/> Rewitness |
| | | <input type="checkbox"/> Not found |
| | | <input type="checkbox"/> Reset at surface |
| Previous Rewitnesses, Restorations and Surveys, etc.: Rewitness Book 2, Page 235; Rewitness Book 7, Page 140, Tillamook County Survey Records. | | |
| Found Monument(s) and Accessories (Condition & Source): Found all four bearing trees set in 1992 as described in Rewitness Book 7, Page 140 at record positions. Found a 3" diameter Oregon State Board of Forestry brass cap and pipe in good condition. Found the original 20" Fir (now a 24" diameter badly rotted snag) with scribes visible, at record position. Also found the original 40" diameter Fir tree (now a 50" diameter badly rotted stump) with no visible marks, at record position. Found two 1952 bearing trees being a 66" diameter Fir stump and a 50" diameter Fir stump, both with visible markings and located at record position. The 65" diameter Fir stump is now a rotten lump. | | |
| Monument Set (Procedures and Description): Not applicable. | Sketch of found Monument: | |
| | | |
| Other new accessories set: Set a 72" hat section post with yellow metal location tag South 2.4'. We also placed a 12" diameter plastic cylinder around the found monument. The plastic cylinder was filled with 60 pounds of concrete. | | |
| New Bearing Trees: No new bearing trees were marked. | | |
| Location & Comments: This corner is located approximately 200' West of Bobcat Cutoff Road at the top of a road cut. | | |
| Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE | | SURVEYOR'S SEAL <i>Danny R. McNutt</i> RENEWAL 12-31-2008 |
| Party Chief: Joe Jensen, PLS 60067, Survey Supervisor | | |
| Notes: | | |
| Witness: Danny R. McNutt, PLS 49230, Tillamook County Surveyor | | |

