



OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: The NE corner of Section 6, T1S, R7W,	TOWNSHIP 1 South	RANGE 7 West	
COUNTY: Tillamook		DATE: 09-15-08	
CORNER DESIGNATION: The Closing corner common to Sections 5 and 6, Township 1 South, Range 7 West, W.M.		(Please check one)	
		<input checked="" type="checkbox"/>	Condition Report Only
		<input type="checkbox"/>	Restoration
		<input type="checkbox"/>	Rewitness
		<input type="checkbox"/>	Unrecorded
		<input checked="" type="checkbox"/>	Reset at surface
Previous Rewitnesses, Restorations and Surveys, etc: Rewitness Book 2, Page 179B; Rewitness Book 7, Page 320, Tillamook County Survey Records.			
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Oregon State Board of Forestry Brass Cap in good condition, 18" feet below the road surface. The monument is stamped as shown hereon. Found all of the bearing trees set by Rewitness Book 7, Page 340 at record position with yellow metal location tags on the trees.			
Monument Set (Procedures and Description): Reset a 2-1/2" diameter Tillamook County Surveyor Aluminum cap on a 5/8" X 8" rebar in 120 pounds of concrete. The monument is set approximately 3" below road surface.		Sketch of Found Monument:	
			
New accessories set: Set a 72° hat section post with yellow metal location tag North 80° East 15.6 feet.			
New Bearing Trees set: No new bearing trees were set.			
Location & Comments: This corner is located in the center of Rogers Road.			
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL  RENEWAL12-31-2008	
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor			
Notes:			
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor.			

Office Use Only

