



**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
Tillamook County Surveyor's Office

<b>SECTION:</b> The East 1/4 corner of Section 19	<b>TOWNSHIP</b> 1 South	<b>RANGE</b> 8 West
<b>COUNTY:</b> Tillamook		<b>DATE:</b> 03-03-09
<b>CORNER DESIGNATION:</b> The East 1/4 corner to Section 19, Township 1 South, Range 8 West, W.M., Tillamook County, Oregon.		<b>(Please check one)</b>
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Reset
		<input type="checkbox"/> Referenced Out
<b>Previous Rewitnesses, Restorations and Surveys, etc.:</b> BLM Field Note Volume: OR-R0575 Page: 0031.0 Map F-40-189; B-530, Tillamook County Survey Records.		
<b>Found Monument(s) and Accessories (Condition &amp; Source):</b> Found a Bureau of Land Management 3-1/4" diameter bronze cap stamped as shown hereon. I placed 120 pounds of concrete inside a 12" diameter plastic cylinder around the found monument. Found a 50" diameter Hemlock tree with a healed face (was a 15" diameter Hemlock bearing North 44 1/2° W 133 lks.) at record position. Searched for, and did not find the 26" diameter Hemlock tree (bearing North 19 1/4 ° W 97 1/2 lks.). Record position falls in existing logging road and is now gone.		
<b>Monument Set (Procedures and Description):</b> Not Applicable.	<b>Sketch of Found Monument:</b> 	
<b>Other new accessories set:</b> Set a 72" Hat Section post with yellow metal location tag North 3.0' from the corner monument.		
<b>New Bearing Trees:</b> *A 20" diameter Alder tree bark scribed "T1SR8W1/4S20BT" with a nail and aluminum washer stamped "Till. Co. Surveyor" set between the 'B & T' which bears North 49° East 15.5'. *A 30" diameter Hemlock tree scribed "T1SR8W1/4S20BT" with a nail and aluminum washer stamped "Till. Co. Surveyor" set between the 'B & T' which bears North 89° East 70.8'. * INDICATES TILLAMOOK COUNTY YELLOW METAL LOCATION POSTER TAG ATTACHED.		
<b>Location &amp; Comments:</b> This corner is located approximately 50' South of an existing logging road.		
<b>Firm / Agency</b> Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE		<b>SURVEYOR'S SEAL</b>
<b>Party Chief:</b> Joe Jensen, PLS 60067, Survey Supervisor		REGISTERED PROFESSIONAL LAND SURVEYOR
<b>Notes:</b>		<i>Joseph V. Jensen</i>
<b>Witness:</b> Danny R. McNutt, PLS 49230, Tillamook County Surveyor		OREGON JANUARY 10, 2006 JOSEPH V. JENSEN 60067

RENEWAL DATE: 06-30-09



**BOOK 7 483**