

**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
Tillamook County Surveyor's Office

<b>SECTION: 13</b>	<b>TOWNSHIP 2 South</b>	<b>RANGE 7 West</b>
<b>COUNTY: Tillamook</b>		<b>DATE: 3-1-10</b>
<b>CORNER DESIGNATION:</b> The Quarter Corner Common to Sections 13 and 14, T. 2 S., R. 7 W., W.M.		<b>(Please check one)</b>
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
<b>Previous Rewitnesses, Restorations and Surveys, etc:</b> BLM Field Notes Volume: OR-R0345 Page 236-237 (GLO 2S7 Pg. 7-8) (1873), Rewitness Book 2 Page 250 (1953), Rewitness Book 6 Page 330 (1987), Map B-3063 (2006), Tillamook County Survey Records.		
<b>Found Monument(s) and Accessories (Condition &amp; Source):</b> Found a 3" dia. O.S.B.F. Brass Cap, flush, in good condition with a rock collar surrounding monument. The monument was set in Rewitness Book 2, Page 250 (1953) and is stamped as shown hereon. Original Post is missing. Found a white painted cedar post 1.0' southwesterly of the monument. (G.L.O.) – Did not find the (10" Hemlock bears N 65° W 43 lks. [28.38']). (G.L.O.) – Did not find the (13" Hemlock bears S 30° E 51 lks. [33.66']). (Book 2, Page 250) – Found 5' tall, badly rotten Fir Stump (was 42" X 30ft. Fir Stub), bears (S 56° W) 46.6' (38.4'), no marks. (Book 2, Page 250) – Found 5' tall, (60" dia. Fir Stump), bears (S 45°30' E) 56.7' (57.4'), scribing visible. (Book 6, Page 330) – Found 17" dia. Fir (was 12") bears (S 85° E 6.7'), healed face and yellow metal location tag. (Book 6, Page 330) – Found 24" dia. Fir (was 16") bears (N 3° W 36.0'), healed face and yellow metal location tag. ( ) Indicates record information, Tillamook County Survey Records. [ ] Indicates converted record value from links to U.S. Survey Feet.		
<b>Monument Set (Procedures and Description):</b>	<b>Sketch of Set Monument:</b>	
<b>New accessories set:</b> Set 120 lbs. of concrete in a 12" diameter cylinder around monument. Set a 72" hat section post with a yellow metal location tag 3.0' North of the monument.		
<b>New Bearing Trees set:</b> 23" dia. D. Fir bears N 42° E 28.4', scribed "T2S R7W 1/4 S13 BT", tagged and painted. 32" dia. D. Fir bears S 67° W 27.9', scribed "T2S R7W 1/4 S14 BT", tagged and painted. All new bearing trees have a nail and aluminum washer marked, "Till. Co. Surveyor", in face of blaze, between the scribed "B" and "T", and a yellow metal location tag affixed.		
<b>Location &amp; Comments:</b> Corner is located approx. 300' West of Murphy Grade Road.		
<b>Firm / Agency</b> <b>Address:</b> TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		<b>SURVEYOR'S SEAL</b>
<b>Party Chief:</b> Joe Jensen, P.L.S. 60067, Survey Supervisor		
<b>Notes:</b> Digital images were taken of the found monument, the record bearing trees and new accessories.		
<b>Witnesses:</b> Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor Michael R. Rice, L.S.I. 16723, Survey Technician		RENEWAL DATE: 08-30-2011

