

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: SW 21	TOWNSHIP 2 South	RANGE 7 West	
COUNTY: Tillamook		DATE: 03-22-10	
CORNER DESIGNATION: The Section Corner common to Sections 20, 21, 29, and 28, T. 2 S., R. 7 W., W.M.		(Please check one)	
		<input type="checkbox"/>	Condition Report Only
		<input type="checkbox"/>	Restoration
		<input checked="" type="checkbox"/>	Rewitness
		<input type="checkbox"/>	Unrecorded
		<input type="checkbox"/>	Reset at surface
		<input type="checkbox"/>	Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0345 Page 294 and 295, (1891); Rewitness Book 2, Page 86 (1951), Tillamook County Survey Records.			
Found Monument(s) and Accessories (Condition & Source): Found a 3" O.S.B.F. Brass Cap, up 0.4', leaning slightly and straightened. The monument was set in Rewitness Book 2, Page 84 (1951). The monument is stamped as shown hereon. (G.L.O.) – Did not find any remains of the original GLO bearing trees. (Book 2, Page 84) – Found rotten 4' tall stump (72" Fir Stump bears S 37° E 109.1'), all scribing visible. (Book 2, Page 84) – Found rotten mound by the road (78" Fir Stump bears N 76° 30' W 122.9'), no marks visible. (Book 2, Page 84) – Found down and rotten (65" Fir Snag bears N 74° 30' E 84.6'), all scribing visible. (Book 2, Page 84) – Found an Alder tree across the river but we didn't tie the location. We did not cross the river due to high water. (8" Alder tree bears S 32° W 125.0'). () Indicates record information, Tillamook County Survey Records. [] Indicates converted value from links to feet.			
Monument Set (Procedures and Description): Not applicable.		Sketch of Found Monument:	
New accessories set: Set 120 lbs. of concrete in a 12" dia. cylinder around monument. Set 72" hat section post with a yellow metal location tag, 3.0' East from monument.			
New Bearing Trees set: *10" dia. Douglas Fir bears S 45° W 28.1', scribed "S29 BT", tagged and painted. *16" dia. Douglas Fir bears N 38° E 29.8', scribed "T2SR7WS21 BT", tagged and painted. Measurements were taken to a nail in the face of the tree. *Indicates a yellow metal location tag affixed and a nail with an aluminum washer marked "Till. Co. Surveyor" between the scribed "B" and "T".			
Location & Comments: Monument is located approximately 50' East of the East Fork Trask Road and North 32° East approximately 60' from the bank of the river. We were not able to obtain a GPS location for this site.			
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL	
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor		<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> REGISTERED PROFESSIONAL LAND SURVEYOR </div>	
Notes: Digital images were taken of the monument, the found bearing trees and the new accessories.			
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor Michael R. Rice, L.S.I. 16723, Survey Technician		<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> OREGON JANUARY 10, 2008 JOSEPH V. JENSEN 60067 </div>	
RENEWAL DATE: 06-30-2011			

