

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: The East 1/4 Corner of Section 31	TOWNSHIP 2 South	RANGE 9 West
COUNTY: Tillamook		DATE: 07-22-10
CORNER DESIGNATION: The one-quarter corner common to Sections 31 and 32, Township 2 South, Range 9 West, W.M., Tillamook County, Oregon.		(Please check one)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Reset at surface
<input type="checkbox"/> Referenced Out		
Previous Rewitnesses, Restorations and Surveys, etc.: BLM Field Notes Volume: OR-R0053 Page 359; Tillamook County GLO Book 2S09, Pg. 18 (1857); Tillamook County Rewitness Card #421, Rewitness Book 3, Page 220 (1965); Map B-499, B-184, B-967, B-1137, Tillamook County Survey Records.		
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Tillamook County Surveyor Brass cap, upright and in good condition, found in a 10" diameter tile filled with concrete and stamped as shown hereon. Found the Hat Section post (set on Rewitness Card #421) at the record position from the monument. Found a 2" iron pipe and set it alongside the found brass cap. Found a 7' tall rotten stump with scribing partially visible and with paddle board nailed to stump (was a 24" Hemlock which bears S 34° W 20.65' scribed "¼ S31BTCS" in Book 3, Page 220). Found a 7' tall rotten stump with scribing partially visible and with paddle board nailed to stump (was a 20" Hemlock which bears S 76° 30' E 13.00' scribed "¼ S32BTCS" in Book 3, Page 220).		
Monument Set (Procedures and Description): N/A	Sketch of Found Monument:	
New accessories set: Attached a new yellow metal location poster marked with the record hat section post information from Rewitness Card #421.		
New Bearing Trees Set: 12" diameter Douglas Fir scribed "T2SR9W1/4S32BT" which bears North 89° East 28.1'. 10" diameter Douglas Fir scribed "T2SR9W1/4S32BT" which bears North 44° East 24.1'. 15" diameter Douglas Fir scribed "T2SR9W1/4S32BT" which bears South 32° East 13.0'. 10" diameter Douglas Fir scribed "T2SR9W1/4S31BT" which bears South 88° West 10.7'. All new bearing trees have a nail and aluminum washer marked, "Till. Co. Surveyor", in face of blaze, between the scribed B and T, and a yellow metal location tag affixed.		
Location & Comments: This corner is located approximately 200 feet South of a logging road in a Hemlock grove at the toe of a steep hillside.		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL
Party Chief: Joe Jensen, PLS 60067, Survey Supervisor		
Notes: Digital images were taken of the monument, the found bearing trees and the new accessories.		
Witness: Danny R. McNutt, PLS 49230, Tillamook County Surveyor;		

