## OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: West 1/4 corner Section 26	TOWNSHIP 3 South	RANGE 7 West		
COUNTY: Tillamook DATE: 05-03-11				
CORNER DESIGNATION: The Quarter Corner Common to Sections 26 and				(Please check one)
27, T, 3 S., R. 7 W. , W.M.				Condition Report Only
				Restoration
			<b>(2</b> )	Rewitness
				Unrecorded
				Reset at surface
				Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0118 Page 0748.00, 1873; BLM Field Notes Volume: OR-R0567 Pages 0130.00, 1957; Survey map number B-590; Survey map number A-760; Survey map number F-11-10, Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found a 3-1/4" Bureau of Land Management brass cap approximately 1.0' above the ground in a rock mound. The found monument is upright and in good condition. The monument is stamped as shown hereon. Placed a 12" diameter plastic cylinder filled with 120 pounds of concrete around the monument. Found an iron fence post 2.0' West of found corner monument.  (BLM Field Notes Volume: OR-R0118 Page 0748.00) – Found a weathered stone with no marks remaining lying along side a rock mound at the found monument. The stone was described as being 14" X 13" X 10" when it was set by surveyor Henry Meldrum in 1873.  (OR-R0567 Pages 0127.00 to 0131.00) – Found a 43" diameter Fir tree with a healed face at record position. The tree has no visible scribe marks but does have a 1957 yellow BLM metal location tag nailed to the tree, (record position and description of the bearing tree from BLM Field Note Volume OR-R0567 Pages 0130.00 = a 35" diameter Fir bearing S.64 ½° W 45 lks = 29.70' marked "1/4 S27 BT").  (OR-R0567 Pages 0127.00 to 0131.00) – Found a 13" diameter Maple tree bearing N 10° E at distance of 37.4'. The tree has no visible markings, (record position and description of the bearing tree from BLM Field Note Volume OR-R0567 Pages 0130.00 = a 11" diameter Maple tree bearing N 9° E 57 lks = 37.62' marked "1/4 S26 BT").				
( ) Indicates record information from BLM				
Monument Set (Procedures and Description): Not applicable.  Sketch			CADASTRAL  T3S R7W  1/4  S27 S26  RR T4ND MANAGEMENT	
New accessories set: Set a 72" hat section post 3.0' South of monument.				
New Bearing Trees set:  A 67" diameter multi-top Maple tree which bears North 15° East 32.7' scribed "T3SR7W1/4S26BT", tagged and painted.				
Location & Comments: The corner is located approximately 250' South of Upper Nestucca River Road and approximately 60' West of a bend in the creek.				
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141  Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor			SURVEYOR'S SEAL REGISTERED	
			PROFESSIONAL LAND SURVEYOR  Jaseph V. Jusen	
Notes: Digital images were taken of the found monument and the record bearing trees and new accessories.  Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor			OREGON JANUARY 10, 2006	
	S. 49230, Tillamook County Survey I. 16723, Survey Technician	or .	JOSEPH V. JENSEN 60067 RENEWAL DATE: 06:30-2011	