

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: The North one-quarter corner of Section 17	TOWNSHIP 1 South	RANGE 8 West	
COUNTY: Tillamook		DATE: 06-21-11	
CORNER DESIGNATION: The one-quarter corner common to Sections 8 and 17, Township 1 South, Range 8 West, W.M., Tillamook County, Oregon.		(Please check one)	
		<input checked="" type="checkbox"/>	Condition Report Only
		<input type="checkbox"/>	Restoration
		<input type="checkbox"/>	Rewitness
		<input type="checkbox"/>	Unrecorded
		<input type="checkbox"/>	Reset
Previous Rewitnesses, Restorations and Surveys, etc.: Please see Tillamook County Rewitness Book 7, Page 77, Tillamook County Survey Records, for the history of this corner.			
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter brass cap in a concrete and 8" monument box as described in Rewitness Book 7, Page 77. The monument box lid and the riser ring were very loose and not in good condition. We determined that the lid and riser ring posed a danger to traffic so I searched for, and checked the reference monuments listed on said rewitness, which were found to be at record position from those values listed in Rewitness Book 7, Page 77. I then pulled the riser ring and lid and filled the monument box with cold patch up to road level. The found 1-1/2" iron pipe at South 00° 18' West 40.58' bears South 66° East approximately 4' from power pole number 085100.			
Monument Set (Procedures and Description): N/A	Sketch of Found Monument: N/A		
Other new accessories set: No new accessories were set.			
New Bearing Trees: No new bearing trees were set.			
Location & Comments: This corner is located approximately in the middle of the Eastbound lane of Oregon State Highway #6, approximately 0.23 miles Southwesterly of Alice's Country House Restaurant.			
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE		SURVEYOR'S SEAL <div style="border: 1px solid black; padding: 5px; display: inline-block; text-align: center;"> REGISTERED PROFESSIONAL LAND SURVEYOR </div> <i>Joseph V. Jensen</i> <div style="border: 1px solid black; padding: 5px; display: inline-block; text-align: center;"> OREGON JANUARY 10, 2006 JOSEPH V. JENSEN 60067 </div> RENEWAL DATE: 06-30-2013	
Party Chief: Joe Jensen, PLS 60067, Survey Supervisor			
Notes: Digital images were taken of the site.			
Witness: Danny R. McNutt, PLS 49230, Tillamook County Surveyor; Michael R. Rice, LSI 16723, Survey Technician.			



BOOK 7 605