

**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
Tillamook County Surveyor's Office

<b>SECTION:</b> The 1/4 corner of Section 3, 2	<b>TOWNSHIP</b> 2 South	<b>RANGE</b> 10 West
<b>COUNTY:</b> Tillamook		<b>DATE:</b> 11-17-08
<b>CORNER DESIGNATION:</b> The Quarter Corner common to Sections 3 and 2, Township 2 South, Range 10 West, W.M., Tillamook County, Oregon.	<b>(Please check one)</b>	
	<input type="checkbox"/>	Condition Report Only
	<input type="checkbox"/>	Restoration
	<input checked="" type="checkbox"/>	Rewitness
	<input type="checkbox"/>	Unrecorded
	<input type="checkbox"/>	Reset at surface
<b>Previous Rewitnesses, Restorations and Surveys, etc:</b> GLO Pg. 4, 2S 10W 1857, 1/4 section corner set from original SE Bearing Tree on map B-555.		
<b>Found Monument(s) and Accessories (Condition &amp; Source):</b> Found a 3" diameter Brass Cap in good condition, in concrete, 0.30 protruding above ground. The monument is stamped as shown hereon. (G.L.O.) – Did not find the 20" Hemlock at record position. (G.L.O.) – Found 40" Hemlock Stump, 4 Feet tall, rotted badly at record position per Book 3, Page 262 (B-555). (Map B-555) – Found 60" Fir Stump, 10 Feet tall, Scribe partially visible, at record position.		
<b>Monument Set (Procedures and Description):</b> Not applicable.	<b>Sketch of Found Monument:</b>	
<b>New accessories set:</b> Set a 72" hat section post with yellow metal location tag South 2.5 feet from corner position. Placed found 4" X 4" White Post next to corner. Set 60 lbs. of concrete in a 12" diameter plastic cylinder around corner. Also, added a rock collar.		
<b>New Bearing Trees set:</b> 11" diameter Hemlock bears N 3° W 3.3 Feet, Scribed "T2S R10W 1/4 S3 BT", No Tag, Painted. 20" diameter Hemlock bears N 70° W 21.0 Feet, Scribed "T2S R10W 1/4 S3 BT", Tagged and Painted. 20" diameter Spruce bears S 53° E 34.3 Feet, Scribed "T2S R10W 1/4 S2 BT", Tagged and Painted.		
<b>Location &amp; Comments:</b> This corner is located approximately 30' South of an old logging road.		
<b>Firm / Agency</b> <b>Address:</b> TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		<b>SURVEYOR'S SEAL</b>  
<b>Party Chief:</b> Joe Jensen, P.L.S. 60067, Survey Supervisor		
<b>Notes:</b>		
<b>Witnesses:</b> Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor. Michael R. Rice, L.S.I. 16723, Survey Technician		

