


USDA-FOREST SERVICE

Index

CORNER RECORD (SEARCH)

File No. Y-22.25 PROJ. NO. Horn CORNER CWESW1/256
 TOWNS. 3 S. RANGE 10 W. R.D. Hebo COUNTY Tillamook GCDB# 625120
 MERID. W.M. FOREST SIU STATE Oregon

CORNER DIAGRAM		DESCRIBE CORNER MONUMENT FOUND	
		Found 3-1/2" AL. Cap on 2-1/2" AL. Pipe, Projecting 1" above ground	
PHOTO IDENTIFICATION DATA		DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND	
Photo No. _____	5/8"	Rebar	(N78-1/2°E) (156.5 FT) Not Found
Filed At. _____	5/8"	Rebar	(N78-1/2°E) (241.2 FT) Not Found
Obj. Ident. _____	5/8"	Rebar	(N47-1/4W) (158.1 FT) Not Found
Ident. By _____	5/8"	Rebar	(N47-1/4W) (222.7 FT) Not Found () = Record Measurement
Signature _____		DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER	
Geodetic COORDINATE POSITION		Follow Farmer Creek Road to the closest point with the West line of section 36 at turnout follow trail east to clearcut and southeast to road, follow State timber road, follow road southerly to first spur on right, follow spur to end at landing covered in slash, on left side of landing is corner and Alder BT	
NAD 83 Epoch:2002 (Conus96)			
North	N45°15'46.2301424"		
West	W123°51'29.6055000"		
El. Height	549.879 iFT		

Signature _____ Title _____ Division _____ Headquarters _____ Date 7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT	REGISTERED PROFESSIONAL LAND SURVEYOR <i>John Ransom</i> OREGON JULY 21, 1992 JOHN C. RANSOM 2561
Cleared brush around corner, painted bearing trees, replace/maintained signs Maintained Line South 1/4 Mile & West 3/8 Mile, Blazed and Posted to standard	

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Marked
 9" Alder Bears N 5-1/2° W - 11.4 FT MKD "CWESW1/256""BT" on Double Blaze With 3/4" Washer "LS2561" On Lower Blz
 7" Fir Bears S 74-1/4° E - 18.0 FT MKD "CWESW1/256""BT" on Double Blaze With 3/4" Washer "LS2561" On Lower Blz
 MEASUREMENTS BY STAFF COMPASS(15-1/2° DEC) AND STEEL TAPE

DONE BY: Jonathan Drew TITLE LSIT DATE FY 2012 PLS NO./AGENCY/STATE _____
 Certified Cor. Record Prepared? Yes Filed At: _____ DATE _____

REMARKS

Line of sight to record rebars is now heavily obstructed by reprod on both sides of line, Searching for these rebar was difficult without the use of EDM or 300' tape neither of which were on hand, new accessories marked and rebar are assumed to be existing as set in 1991 survey
 Geodetic Coordinates Processed from RTK& static GPS from OPUS adjusted Base Station

Index File No Y-22.25 T. 3 S. R. 10 W. Merid. W.M. Cor. CWESW1/256

