

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office


SECTION: 17	TOWNSHIP 4 South	RANGE 7 West
-------------	------------------	--------------

COUNTY: Tillamook	DATE: 10-13-15
-------------------	----------------

CORNER DESIGNATION: The One-Quarter corner common to Sections 17 and 20, Township 4 South, Range 7 West, W. M.	(Please check one) <input type="checkbox"/> Condition Report Only <input type="checkbox"/> Restoration <input checked="" type="checkbox"/> Rewitness <input type="checkbox"/> Unrecorded <input type="checkbox"/> Brass Cap set at surface <input type="checkbox"/> Referenced Out
---	---

Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Note Volume: OR-R0118 Page 803; Tillamook County Rewitness Book 3, Page 87; Rewitness Book 6, Pages 176A and 176B; Tillamook County Survey Map B-590; Yamhill County Survey Map B-3540.

Found Monument(s) and Accessories (Condition & Source): Found a 3-1/4" diameter BLM Brass Cap on a 28" x 2-1/2" iron post. The found monument is stamped as shown hereon. Found a 21" diameter, 1' tall Douglas Fir stump with healed face at record position (was a 9" diameter Douglas Fir tree bearing North 22° West 101-1/2 links = 66.99 marked "1/4 S17 BT") see Rewitness Book 3, Page 87. Found a 21" diameter, 7' tall Douglas Fir stump with a healed face and yellow metal location tag at record position (was an 8" diameter Douglas Fir tree bearing South 1-1/2° East 82-1/2 links = 54.45' see Rewitness Book 3, Page 87).

Monument Set (Procedures and Description):	Sketch of Found Monument: 
---	--

New accessories set: Set a 72" long galvanized steel post with yellow metal location tag North 2.0' from the monument.

New Bearing Trees set: 10" diameter Douglas Fir tree scribed "T4SR7WS17BT" which bears North 64° 30' West 23.3'; a 10" diameter Douglas Fir tree scribed "T4SR7WS17BT" which bears North 62° East 24.5'.

Location & Comments:	
---------------------------------	--

Firm / Agency: Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141
Party Chief: Joe Jensen, PLS 60067, Deputy County Surveyor and Survey Supervisor;
Notes: Digital images were taken of the monument and the accessories.
Witnesses: Danny R. McNutt, PLS 49230, Tillamook County Surveyor

SURVEYOR'S SEAL

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Joseph V. Jensen

OREGON
 JANUARY 10, 2018
 JOSEPH V. JENSEN
 60067

RENEWAL DATE: 08-30-17

