



OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 2	TOWNSHIP: 3S	RANGE: 8W
COUNTY: TILLAMOOK		DATE: JUNE. 20, 2016
CORNER DESIGNATION: CENTER SOUTH 1/16 CORNER OF SECTION 2, T3S, R8W.		(Please Check One)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Not Found
		<input type="checkbox"/> Reset
Referenced Out		
Previous Rewitnesses, Restorations, Surveys, etc.:		
Found Monument(s) and Accessories(Condition & Source): FOUND OREGON STATE BOARD OF FORESTRY BRASS CAP STAMPED "CS 1/16 S2 1973 RS707" ON 1 1/2" IRON PIPE, 0.2' ABOVE GROUND, FROM WHICH: 12" (6") ROTTEN HEMLOCK STUMP WITH TIN COVER BEARS (S 36° E 13.3'); 26" (8") HEMLOCK WITH HEALED FACE BEARS (N 79° W 18.3'), SEE MAP A-2537.		
Monument Set(Procedures & Description):		
Other New Accessories Set: CARSONITE POST 1' NORTH		
New Bearing Trees: 12" DOUG FIR, SCRIBED "CS 1/16 S2 BT" BEARS S 23° W 23.51' TO BRASS NAIL AND WASHER STAMPED "LS 2507" BETWEEN THE B & T.		
Location & Comments: ON RIDGE 400' FROM ROAD INTERSECTION	Surveyor's Stamp	
Firm/Agency: BAYSIDE SURVEYING		
Address: 11765 HWY 101 SOUTH TILLAMOOK, OR 97141		
Party Chief: TERRY JONES		
Notes: FILE NAME rewitness\T3S-R8W-S2-CS1-16.xls	Office Use Only	
Witness(es): TLJ/DWE	