

OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 36 AND 31	TOWNSHIP: 2N	RANGE: 8W AND 7W
COUNTY: TILLAMOOK		DATE: JUNE 21, 2016
CORNER DESIGNATION: 1/4 CORNER COMMON TO SECTION 36, T2N, R8W AND SECTION 31, T2N, R7W		(Please Check One)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Not Found
		<input type="checkbox"/> Reset
		<input type="checkbox"/> Referenced Out
Previous Rewitnesses, Restorations, Surveys, etc.: 		
Found Monument(s) and Accessories(Condition & Source): FOUND OREGON STATE BOARD OF FORESTRY ALUMINUM CAP ON 1 1/2" ALUMINUM PIPE, STAMPED "T2N R8W R7W 1/4 S36 S31 1990 LS 1998", FROM WHICH: BRASS CAP ON 1 1/2" GALVANIZED IRON PIPE, STAMPED "WC 1/4 S36 S31 RM 5FT S 1952 2311" WITH CARSONITE POST 1.5' SW BEARS NORTH 5'; 45" FIR STUMP WITH SCRIBING VISABLE BEARS N 25° E 22.4' FROM WITNESS CORNER; 12" (10") DUG FIR WITH HEALED FACE BEARS N 43 1/2° E 12.8'; 14" (11") DOUG FIR WITH HEALED FACE BEARS N 82° W 13.7'. SEE REWITNESS BOOK 7, PAGE 39		
Monument Set(Procedures & Description):		
Other New Accessories Set: CARSONITE POST 1.5' SOUTH		
New Bearing Trees:		
Location & Comments: MONUMENT IS ±80' NORTH OF ROAD, 80' WEST OF ROAD, 25' SOUTH EAST-WEST RIDGE.		Surveyor's Stamp RENEWAL DATE 6-30-17
Firm/Agency: BAYSIDE SURVEYING		
Address: 11765 HWY 101 SOUTH TILLAMOOK, OR 97141		
Party Chief: TERRY JONES		
Notes: FILE NAME rewitness\T2N-R7+8W-S31-S36-1-4.XLS		Office Use Only
Witness(es): TLJ/DWE		