



OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 7	TOWNSHIP: 1S	RANGE: 9W
COUNTY: TILLAMOOK		DATE: JUNE 29, 2016
CORNER DESIGNATION: SE 1/16 Corner		(Please Check One) <input type="checkbox"/> Condition Report Only <input type="checkbox"/> Restoration <input checked="" type="checkbox"/> Rewitness <input type="checkbox"/> Not Found <input type="checkbox"/> Reset <input type="checkbox"/> Referenced Out
Previous Rewitnesses, Restorations, Surveys, etc.:		
Found Monument(s) and Accessories(Condition & Source): FOUND OREGON STATE BOARD OF FORESTRY BRASS CAP ON 1 1/2" GALVANIZED IRON PIPE STAMPED "SE 1/16 S7 1967 RS 707", 0.1' ABOVE GROUND, FROM WHICH: SET CARSONITE POST 1.5' NORTH; GONE: (11") HEMLOCK, BEARS (N6 1/2°E 28.1'); GONE: (17") HEMLOCK, BEARS (N81° E22.7'); FOUND: ROTTEN, WHITE 4" x 4" POST ALONGSIDE, SEE MAP B-535.		
Monument Set(Procedures & Description):		
		
Other New Accessories Set:		
New Bearing Trees: MARKED NEW BEARING TREES: 19" HEMLOCK TREE SCRIBED "SE 1/16 57 BT", BEARS S66° W 29.90', TO BRASS NAIL AND WASHER "LS 2507" BETWEEN B & T; 38" SPRUCE TREE SCRIBED "SE 1/16 57 BT", BEARS N30° W 49.20', TO BRASS NAIL AND WASHER LS 2507.		
Location & Comments: CORNER IS ON TOP RIDGE THAT RUNS S14° W; 20' WEST OF THE CENTER OF A NORTH-SOUTH ROCK ROAD.		Surveyor's Stamp  renewal date 6-30-17
Firm/Agency: BAYSIDE SURVEYING Address: 11765 HWY 101 SOUTH TILLAMOOK, OR 97141		
Party Chief: TERRY JONES		
Notes: FILE NAME rewitness\T1S-R9W-S7-SE.xls		
Witness(es): TLJ/DWE		Office Use Only 