

10
15

TILLAMOOK COUNTY REWITNESS # 194
 SEC. 10
 COR. 15 T 15 R 9 W., WM.

HISTORICAL: PROPORTION CORNER G.L.O. Pg. 140 159


BK. Pg.	MAPS
3 148	A-1100
	B-672

FD. CONDITION	FOUND	FOUND	FOUND
GOOD	2 1/2" I.P. WITH 3" BRASS CAP	G.L.O. Pg. 140	
22" FIR STUMP SCRIBE MARKS BARELY VISIBLE ON ROTTEN FACE	22" FIR	N. 67° W. 8 1/2 LKS.	G.L.O. Pg. 140
FD. NOW 10" STUMP SCRIBING VISIBLE ON ROTTEN BURNT FACE	12" FIR	S. 58° E. 37 LKS.	G.L.O. Pg. 140

COMMENTS:

REWITNESS

1 SET 10" CONCRETE CYLINDER AROUND FOUND 2" I.P. WITH 3" U.S. CADASTRAL BRASS CAP.



* 72" Hat Section SOUTH 19 FEET

NEW ACCESSORY:

* 8" SPRUCE	N. 10° W. 866 FT.	1/4 S10 B-T CS
* 10" SPRUCE	N. 85° W. 184' FT.	1/4 S10 B-T CS

COMMENTS: THIS CORNER IS LOCATED ON THE MAIN RIDGE DIVIDING THE KILCHIS AND WILSON RIVER DRAINAGES, AND † 300' WEST OF A GRAVEL SPUR LOGGING ROAD.

IN THE PRESENCE OF: DAN MENUTT AL DVORAK

DATE: 5-12-88

PHOTO#:

* = County corner tag affixed.

TITLE