

TILLAMOOK COUNTY REWITNESS #209

~~SEC. S~~ SEC. S 16 | 15
 Section COR. 21 | 22 T 15 R 9 W., WM.
~~SEC. S~~

HISTORICAL: GLO-1857-Page 58-H. Meldrum
 Bk 1 Page 4 & Bk 4 Page 98 -- W.E. Anderson / F.L. Smith 1960
 Bk 4 Page 16 -- 1905 -- Jacobs & Davis
 MAPA-700 -- J. Carlich -- 1957 - subdivision sec 22
 MAP A-1099 -- R.A. Morris -- 1963 -- Subdivision sec 16

CONDITION

FOUND:


	2" Iron Pipe with plug and nail	(o.k. 1972)
barkscribed S22 BT ^{A. Dunne 1963}	7" Willow with O.S.B.F. Tag (1963) N89°E 5 81	(Good)
^{1972 field check} NOW GONE S21 BT ^{G. Arthur 1969}	9" Willow S05°W 2 96	(Gale Arthur 1969)
NOW GONE S16 BT ^{G. Arthur 1969}	9" Willow N55°W 3 85	Top broke off -- Stump still standing -- (Gale Arthur 1969)
NOW GONE S15 BT ^{S. Skinner 1965}	8" Willow N32°E 11 69	Tree completely uprooted -- Now bears N30°E 10 5
12" Alder S35°E Now gone	12" Alder S01°E Now gone (STAN. SKINNER 1965)	

Fd. Cedar post at East-Northeast 0 5 marked S21/S22/S15/S16

COMMENTS: Hat section North 1 5 Gale Arthur 1969

REWITNESS

1 SET 2" Iron Pipe with Brass Cap 8" above ground
 Carved cedar 4" 4" x 48" Post ~~SEC. S~~ E.N.E. 0 5 feet
 *96 " Hat Section S. E 1 5 feet



NEW ACCESSORY:

6" Willow Bark Scribed	N52E 6 93	S15 BT (Good) ^{o.k. 1972}
10" Tile Filled With	concrete	
Cor Tags	2 BT's	

COMMENTS: Corner is located on south side of Wilson river in a group of willows and blackberrys area has recently been cleared

IN THE PRESENCE OF: Gale Arthur
 G.W. Urrey

DATE: 1970 PHOTO#: _____

* = County corner tag affixed. Gwu TITLE