

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Index File No. _____ Tract or Survey No. _____ Cor. No. A-13

T 35 R. 9W R.D. Hebo County TILLAMOOK # 488

Merid. WILL. N.F. SIUSLAW State ORE.

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

LINCOLN WILKES, GLO 1896 SET CEDAR POST AND MARKED:
12" ALDER, S. 24° E., 40 LKS.
12" ALDER, S. 54° W., 14 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FOUND 3 X 3 X 60 POST (NOT ORIGINAL) IN POOR CONDITION
FOUND 2" ALDER, S. 54° W., 9² FT. WITH VISIBLE BUT ILLEGIBLE SCRIBE MARKS IN THE BARK.
FOUND OLD SE BT FALLEN ON THE GROUND IN DECAYED CONDITION.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

I MARK 36" FIR, S. 79° E., 81² FT. MARKED: "S3 CC BT CS"; PUT BT SIGN ON TREE.
SET ALUMINUM POST WITH "PENALTY TO DESTROY" SIGN ATTACHED AT CORNER POINT.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature Leonard Whitmore Title Forestry Tech Division Timber Headquarters Hebo Date 11-23-69 7100-52 (3/68)

REWITNESS

I SET _____ "x" _____ "x" _____ " Post N.W. _____ feet
" Hat Section S. E.

NEW ACCESSORY:

COMMENTS: _____

IN THE PRESENCE OF: _____

DATE: _____

PHOTO#: 250

LEWIS & CLARK COUNTY CORNER TAG AFFIXED

LITWOCK COUNTY SEWELLER TITLE

Whitmore is Deputy Co Surveyor qualified to re-locate old post from original monument