

U. S. Department of Agriculture
FOREST SERVICE

Recorded

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 3 S. R. 10 W. Mer.

Section 14 Corner common to Sections

10, 11, 14, and 15

Corner consists of a Post (not chain) (not in place)

State condition

Dimensions above ground 20 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

N	W	S	E
	NW	SW	SE
			NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Hemlock oaks lives are dead

Diameter 32 Hemlock 519.5

Bearing S 41° W

Distance 34.5

Do you believe this to be a genuine Land Office Corner? YES

If not, why?

Maria Whitmore

(Signature)

4-8-48


(Date)

(This)

T. 3 S. R. 10 W.

Mer. WWH

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a Hemlock B.T. tree 32 inches diameter, on the North side of bearing tree from which this Corner bears N 41° E, 34 Lks. Chains. (Bearing) (Distance)

Section line marker between Secs. _____ and _____ is on a _____ on the _____ (Name of road, trail, etc.) located _____ chains E, F, N, S, from Sec. Cor.; $\frac{1}{2}$ Cor.; Witness Cor. (Cross out nonapplicable)

Give any further facts needed to find Corner again:

Follow blazed line south from the SW corner of Herman Tahl ranch. Top ridge.

Maria Whitmore
4-8-48
D. S. GOVERNMENT PRINTING OFFICE 16-12740-1

#608